

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26K-795

Location ID: 334415

Date: 8/30/2024



Wellheads – Photo #03286



Separators – Photo #03294

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26K-795

Location ID: 334415

Date: 8/30/2024



Tank Battery – Photo #03288



ECD – Photo #03293



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26K-795

Location ID: 334415

Date: 8/30/2024



Spill Kit/Methanol Tank – Photo #03292



Pig Station – Photo #03296



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26K-795

Location ID: 334415

Date: 8/30/2024



Stored Equipment – Photo #03291



Unsecured Equipment/Wildlife Entry Hazard – Photo #03295



## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Battlement Mesa/26K-795

Location ID: 334415

Date: 8/30/2024



Unsecured Equipment/Wildlife Entry Hazard – Photo #03289



Unsecured Equipment/Wildlife Entry Hazard – Photo #03290