

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location ID: 334826

Date: 9/5/2024



Location Entrance – Photo #03309



Wellheads – Photo #03310

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location ID: 334826

Date: 9/5/2024



Separators – Photo #03313



Tank Battery – Photo #03314

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/31SESW

Location ID: 334826

Date: 9/5/2024



Open Wellhead Cellar – Photo #03311



Open Wellhead Cellar – Photo #03312