

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

## ECMC RECEPTION

Receive Date:

01/10/2024

Document Number:

403649947

## ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

**Operator Information**

ECMC Operator Number: 47120 Contact Person: Erik Mickelson  
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306  
Address: P O BOX 173779 Fax: ( )  
City: DENVER State: CO Zip: 80217-3779 Email: Erik\_Mickelson@oxy.com

**Identification Information**

API Number: 05 - - ECMC Facility ID: 485209 Initial Form 19 or 27 Document number:  
Facility Name: LIZZY Facility Number: 8-36HZ Facility Type: LOCATION  
Location QtrQtr: SENE Section: 36 Township: 1N Range: 68W Meridian: 6  
County: WELD Field Name:  
Federal, Indian or State Lease Number:

## Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional  
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

## Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 772150 Facility Name: Robbins 269376 Facility Type: Domestic Well  
Location: QtrQtr: SENW Sec: 1 Twp: 1S Range: 68W Meridian: 6  
County Name: ADAMS Latitude: 39.995173 Longitude: -104.949978

**Sample Information:**

The following Sample Information has been reviewed by the ECMC:

Batch ID: 115949 Document Name: Size of file in bytes: 35840 File Name: 2023\_10\_10\_Robbins 269376 Isotech NG4  
ECMC.xls  
SampleType: Matrix:  
Facility ID: 772150 Sample ID: 655206 Sample Name: Robbins 269376 Sample Date: 10/10/2023  
Collection Point: Dom Matrix: WATER Pre Post: Voluntary baseline sample  
Project Number: Remediation Number: Complaint Number: NOAV Number:  
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 895308

Batch ID: 115949		Document Name: Size of file in bytes: 35840		File Name: 2023_10_10_Robbins 269376 Isotech NG4 ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772150	Sample ID: 655205	Sample Name: Robbins 269376		Sample Date: 10/10/2023	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 895308		

Batch ID: 115947		Document Name: Size of file in bytes: 25600		File Name: 2023_10_10_Robbins 269376 SGS DRO ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772150	Sample ID: 655203	Sample Name: Robbins 269376		Sample Date: 10/10/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59245-1		

Batch ID: 115946		Document Name: Size of file in bytes: 74752		File Name: 2023_10_10_Robbins 269376 SGS ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772150	Sample ID: 655202	Sample Name: Robbins 269376		Sample Date: 10/10/2023	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59245-1		

Batch ID: 115948		Document Name: Size of file in bytes: 31232		File Name: 2023_10_10_Robbins 269376 Trip Blank SGS ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 772150	Sample ID: 655204	Sample Name: Robbins 269376		Sample Date: 10/10/2023	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary baseline sample			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA59248-1		

### Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772150	403649961	2023_10_10_Robbins 269376 SGS.pdf	Analytical Laboratory Report	PDF
772150	403649957	2023_10_10_Robbins 269376 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772150	403649970	2023_10_10_Robbins_269376_Spigot.jpg	Photographs	JPG
772150	403649974	2023_10_10_Robbins_269376_Wellhead_Loc.jpg	Photographs	JPG
772150	403649966	2023_10_10_Robbins_269376_FS_ECMC.pdf	Field Data Report	PDF
772150	403649952	2023_10_10_Robbins 269376 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772150	403649973	2023_10_10_Robbins_269376_Wellhead.jpg	Photographs	JPG
772150	403649969	2023_10_10_Robbins_269376_PrePostPurge.jpg	Photographs	JPG
772150	403649971	2023_10_10_Robbins_269376_Spigot_Loc.jpg	Photographs	JPG

### Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	09/10/2024
Total: 1 comment(s)		