

# Inspection Photos

September 4th, 2024

Operator: American Helium Operating - 10841

Location ID: 334296

Inspection Document #: 714001172

San Miguel County, CO

Township: SWSE 34 44N 16W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Andy Mesa Federal 34, 58  
Location ID: 334296



9/4/24  
+38.025093,-108.617034  
308° NW



Photo 1. View of well disturbance taken from the access point facing center.

Inspection Photos  
Location Name: Andy Mesa Federal 34, 58  
Location ID: 334296



**Photo 2.** Signs at produced water tanks need to be updated. Per rule 605.g buying operator has 60 days from approved form 9 date to replace or update signs on location.

Inspection Photos

Location Name: Andy Mesa Federal 34, 58

Location ID: 334296



9/4/24  
+38.024493,-108.618565  
219° SW



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** View of the southern interim reclamation area facing southwest.

API #: 113-06111, 06139

Inspection Photos

Location Name: Andy Mesa Federal 34, 58

Location ID: 334296



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Reference area comprised of Black sage, Broom snakeweed and Intermediate wheatgrass.

API #: 113-06111, 06139