

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 316837

Inspection Document #: 714001177

San Miguel County, CO

Township: SENE 28 44N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Andy Mesa Federal 37
Location ID: 316837



Photo 1. View of the well disturbance taken from the access point facing center.



API #: 113-06126

Inspection Photos

Location Name: Andy Mesa Federal 37

Location ID: 316837



9/4/24

+38.047731,-108.633619

89° E

Photo 2. Erosion and sediment transport observed in the eastern portion of the disturbance. Stabilization/Stormwater BMPs needed in this area.

Inspection Photos

Location Name: Andy Mesa Federal 37

Location ID: 316837



9/4/24
+38.047901,-108.634184
154° SE



9/4/24
+38.048074,-108.634269
172° S

Photo 3. Several erosional channels observed in the southern portion of the disturbance. Stabilization/stormwater BMPs needed in this area.

Inspection Photos

Location Name: Andy Mesa Federal 37

Location ID: 316837



Photo 4. Signs at produced water tanks need to be updated. Per rule 605.g buying operator has 60 days from approved form 9 date to replace or update signs on location.

Inspection Photos

Location Name: Andy Mesa Federal 37

Location ID: 316837



9/4/24

+38.048246,-108.634482

305° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area comprised of Black sage, Broom snakeweed, Fourwinged saltbrush and Western wheatgrass.

API #: 113-06126