

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 316803

Inspection Document #: 714001178

San Miguel County, CO

Township: SWSW 21 44N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Andy Mesa Federal 6
Location ID: 316803



9/4/24
+38.054541,-108.645921
197° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the northern edge facing center.

API #: 113-06005

Inspection Photos

Location Name: Andy Mesa Federal 6

Location ID: 316803



Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo east. Note: risers in the foreground are associated with an active pipeline ROW in the northern portion of the project area.

Inspection Photos
Location Name: Andy Mesa Federal 6
Location ID: 316803



Photo 3. Cardinal photos taken from the center of the project area, left photo facing south, right photo facing west. Note: Previous reclamation seeding was unsuccessful with bare soils dominating reclaimed areas, additional reclamation work is needed. Bare soils need stabilization until location is stabilized with desirable vegetation.

Inspection Photos
Location Name: Andy Mesa Federal 6
Location ID: 316803



9/4/24
+38.054919,-108.646032
296° NW