

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 316836

Inspection Document #: 714001179

San Miguel County, CO

Township: NESW 20 44N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Andy Mesa Federal 29
Location ID: 316836



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Andy Mesa Federal 29
Location ID: 316836




Photo 2. Well signs and produced water tanks/placards are not updated. Buying operator has 60 days from approved form 9 date to update signs/placards on location.

Inspection Photos
Location Name: Andy Mesa Federal 29
Location ID: 316836

9/4/24
+38.057980,-108.658657
313° NW



Photo 3. View of the northern interim reclamation area facing northwest.

Inspection Photos
Location Name: Andy Mesa Federal 29
Location ID: 316836

9/4/24
+38.057980,-108.658657
26° NE

