

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 316826

Inspection Document #: 714001180

San Miguel County, CO

Township: SESE 18 44N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fossil Federal 2-18
Location ID: 316826



Photo 1. View of the well disturbance taken from the access point facing center.



API #: 113-06099

Inspection Photos
Location Name: Fossil Federal 2-18
Location ID: 316826



9/4/24
+38.066778,-108.669049
354° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of Weedy kochia and Russian thistle debris dominating the well pad.

API #: 113-06099

Inspection Photos
Location Name: Fossil Federal 2-18
Location ID: 316826



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Tank labels/placards have not been updated. Buying operator has 60 days from approved form 9 date to updated signs on location.

API #: 113-06099

Inspection Photos
Location Name: Fossil Federal 2-18
Location ID: 316826



Photo 4. Reference area comprised predominantly of Black sage.

