

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 333206

Inspection Document #: 714001181

San Miguel County, CO

Township: NENE 19 44N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fossil Federal 1, 2 4-19
Location ID: 333206



+38.065598, -108.671833



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Fossil Federal 1, 2 4-19
Location ID: 333206

9/4/24
+38.066169,-108.671999
43° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of Weedy kochia and Russian thistle debris dominating the well pad.

API #: 113-06073, 06083, 06118

Inspection Photos

Location Name: Fossil Federal 1, 2 4-19

Location ID: 333206



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Well signs, tank placards need to be updated. Buying operator has 60 days from approved form 9 date to updated signs on location.

API #: 113-06073, 06083, 06118

Inspection Photos
Location Name: Fossil Federal 1, 2 4-19
Location ID: 333206

9/4/24
+38.066289,-108.672335
181° S



Photo 4. View of the southern interim reclamation area facing south.

Inspection Photos
Location Name: Fossil Federal 1, 2 4-19
Location ID: 333206



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of reference area comprised of Indian ricegrass, Black sage and Broom snakeweed.

API #: 113-06073, 06083, 06118