

**Inspection Photos**  
**Location Name: Elton N. Miller E1**  
**Location ID: 318528**



**Photo 1 Location with overgrown vegetation around it.**



**Photo 2 Wellhead with overgrown vegetation around it.**



**Inspection Photos**  
**Location Name: Elton N. Miller E1**  
**Location ID: 318528**



**Photo 3 Wellhead sign**



**Photo 4 Old pump jack house has been removed.**





**Inspection Photos**  
**Location Name: Elton N. Miller E1**  
**Location ID: 318528**



**Photo 5 Trash & debris along the ground where the old PJ housing sat.**



**Photo 6 Old pump jack house has been removed.**