

Inspection Photos
Location Name: Elton N. Miller E1 Battery
Location ID: 318528



Photo 1 Tank battery location.



Photo 2 TB.

Inspection Photos
Location Name: Elton N. Miller E1 Battery
Location ID: 318528



Photo 3 Tank battery sign.



Photo 4 Stained soil by the TB valve.



Inspection Photos
Location Name: Elton N. Miller E1 Battery
Location ID: 318528



Photo 5 Stained soil by the TB valve.




Photo 6 No vent screen/cap for wild life .

Inspection Photos
Location Name: Elton N. Miller E1 Battery
Location ID: 318528



Photo 7 Horizontal heated separator, Gas Meter Run & telemetry.



Photo 8 Gas Meter Run.

Inspection Photos
Location Name: Elton N. Miller E1 Battery
Location ID: 318528



Photo 9 Trash, doors lying on the ground & wiring.




Photo 10 Unused flow line riser.