

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Unlabeled. Open to wildlife.

Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420



No well sign. On the ground.



Well sign debris

Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420



Debris



No secondary containment

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Debris

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Open to wildlife

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Unregistered pit

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Open to wildlife

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Unlabeled tank

Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420



Staining. Open to wildlife.



Tank missing required information

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Open end load line

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Staining



Debris

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris. Staining.



Tank missing required information

Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420



Debris



Debris

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Debris



Debris

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Location from Northwest corner

Location from Northeast corner

**Antler Energy LLC
Pole Gulch Unit 2
Location ID: 313420**



Location from Southeast corner

Location from Southwest corner