

Inspection Photos

Operator: **VISION ENERGY LLC– 10770**

Location Name: **CAMP GULCH UNIT-FEDERAL 3-22-8-103**

Location ID: **312578** API #: **05-077-08556**

Inspection Date: **9/4/2024** Inspection Doc#: **693807715**



Wellhead



**Separator with sign.
Tank battery**

Inspection Photos

Operator: VISION ENERGY LLC– 10770

Location Name: CAMP GULCH UNIT-FEDERAL 3-22-8-103

Location ID: 312578 API #: 05-077-08556

Inspection Date: 9/4/2024 Inspection Doc#: 693807715



Heated Separator



Meter housing

Inspection Photos

Operator: VISION ENERGY LLC– 10770

Location Name: CAMP GULCH UNIT-FEDERAL 3-22-8-103

Location ID: 312578 API #: 05-077-08556

Inspection Date: 9/4/2024 Inspection Doc#: 693807715



Pit with fence



Location overview looking W