

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 333072

Inspection Document #: 714001198

San Miguel County, CO

Township: NWNW 19 44N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fossil Federal 5, 5-19
Location ID: 333072



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: Fossil Federal 5, 5-19
Location ID: 333072

9/4/24
+38.063404,-108.681784
321° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of several piles of bare/loose soils stored around the location with no erosion/sediment transport BMPs in place.

API #: 113-06069, 06120

Inspection Photos

Location Name: Fossil Federal 5, 5-19

Location ID: 333072



9/4/24

+38.063639,-108.681939

320° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of the northern interim reclamation area facing northwest.

API #: 113-06069, 06120

Inspection Photos

Location Name: Fossil Federal 5, 5-19

Location ID: 333072



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of reference area comprised of Rabbitbrush, Juniper and Fourwinged saltbrush.

API #: 113-06069, 06120