

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 316824

Inspection Document #: 714001199

San Miguel County, CO

Township: NWSE 18 44N 16W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fossil Federal 1-18
Location ID: 316824



9/4/24
+38.070143,-108.674270
322° NW

Photo 1. View of the well pad taken from the access point facing center.



9/4/24
+38.070328,-108.674250
158° S

American Helium
Fossil Federal #1-18
(NW SE) Sec 18, T44N-R16W
Lat. N 38.07051°/Long. W -108.67462°
SHL: 1677' FSL & 1972' FEL
Lease # COC-61577
API # 05-113-06096-CR R25
San Miguel County-- CR R25
Emergency # (435) 631-2239 or 911

Inspection Photos
Location Name: Fossil Federal 1-18
Location ID: 316824



Photo 2. View of weedy Kochia debris observed on the active pad.

Inspection Photos
Location Name: Fossil Federal 1-18
Location ID: 316824



Photo 3. Tank signs/placards need to be updated.



Inspection Photos
Location Name: Fossil Federal 1-18
Location ID: 316824



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of plastic container filled with what appears to be contaminated soils.

API #: 113-06096

Inspection Photos
Location Name: Fossil Federal 1-18
Location ID: 316824



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of reference area comprised of Fourwinged saltbrush, Winterfat and Black sage.

API #: 113-06096