

Inspection Photos

September 4th, 2024

Operator: American Helium Operating LLC - 10841

Location ID: 316822

Inspection Document #: 714001200

San Miguel County, CO

Township: NWSE 13 44N 17W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Fossil Federal 1-13
Location ID: 316822



9/4/24
+38.075989,-108.688904
352° N



9/4/24
+38.076069,-108.688823
86° E

Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 113-06091

Inspection Photos
Location Name: Fossil Federal 1-13
Location ID: 316822



Photo 2. Tank signs/placards need to be updated.

Inspection Photos
Location Name: Fossil Federal 1-13
Location ID: 316822



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Group of tamarisk observed along the access road.

API #: 113-06091

Inspection Photos
Location Name: Fossil Federal 1-13
Location ID: 316822



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of western interim reclamation area facing southwest.

API #: 113-06091

Inspection Photos
Location Name: Fossil Federal 1-13
Location ID: 316822



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of reference area comprised of Fourwinged saltbrush, Winterfat and Black sage.

API #: 113-06091