

Inspection Photos
Location: Cake Walk 13-29
Location ID: 308983
API # 05-071-08916



Photo 1 –Well placard on meter run.



Photo 2 – Wellhead and equipment.

Inspection Photos
Location: Cake Walk 13-29
Location ID: 308983
API # 05-071-08916



Photo 3 – Meter house and equipment



Photo 4 – Skid Pan full of oil mixed water, Stained soils observed at base

