

## Inspection Photos

Location: Chinamans Federal 24-19 and Chinamans Federal 24-19 TR

Location ID: 333534

API # 05-071-06589 and TR API # 05-071-07941



Photo 1 –Well placard on meter house



Photo 2 – Well placard on meter house



## Inspection Photos

Location: Chinamans Federal 24-19 and Chinamans Federal 24-19 TR

Location ID: 333534

API # 05-071-06589 and TR API # 05-071-07941



**Photo 2 – Original wellhead, Russian Thistle near wellhead and equipment**



**Photo 3 – Pit Facility ID 263628**



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources



## Inspection Photos

Location: Chinamans Federal 24-19 and Chinamans Federal 24-19 TR

Location ID: 333534

API # 05-071-06589 and TR API # 05-071-07941



**Photo 4 –TR wellhead, Russian Thistle near wellhead and equipment**



**Photo 5 – Pit Facility 278527, Russian Thistle is lining bottom of pit**



## Inspection Photos

Location: Chinamans Federal 24-19 and Chinamans Federal 24-19 TR

Location ID: 333534

API # 05-071-06589 and TR API # 05-071-07941



**Photo 6 –Debris in pit**



**Photo 7 –Location, there is Russian Thistle/Tumbleweed throughout the location and access road**