

Inspection Photos
Location: Jalapeno 34-19 and Jalapeno 34-19 TR
Location ID: 334227
API # 05-071-06526 and TR API # 05-071-06739



Photo 1 –Well placard on meter house



Photo 2 – Wellhead and equipment

Inspection Photos

Location: Jalapeno 34-19 and Jalapeno 34-19 TR

Location ID: 334227

API # 05-071-06526 and TR API # 05-071-06739



Photo 2 – Noxious weeds, Canada Thistle and Mullein on eastern edge of location



Photo 3 – Noxious weeds, Canada Thistle on eastern edge of location



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location: Jalapeno 34-19 and Jalapeno 34-19 TR

Location ID: 334227

API # 05-071-06526 and TR API # 05-071-06739



Photo 4 –TR wellhead



Photo 5 – Pit Facility 263027, active pit

Inspection Photos

Location: Jalapeno 34-19 and Jalapeno 34-19 TR

Location ID: 334227

API # 05-071-06526 and TR API # 05-071-06739



Photo 6 –Stormwater is running across access road causing erosion



Photo 7 –Stormwater is running down the access road causing erosion