

Inspection Photos

Location: Banchee 41-30 and Banchee 41-30 TR

Location ID: 334234

API # 05-071-06444 and TR API # 05-071-06736



Photo 1 –Well placard on meter house




Photo 2 – Wellhead and equipment. Packing leak, produced water.

Inspection Photos

Location: Banchee 41-30 and Banchee 41-30 TR

Location ID: 334234

API # 05-071-06444 and TR API # 05-071-06736



Photo 2 – Pit Facility ID 113393, L-shaped pit



Photo 3 – Pit Facility ID 113602, L-shaped pit

Inspection Photos

Location: Banchee 41-30 and Banchee 41-30 TR

Location ID: 334234

API # 05-071-06444 and TR API # 05-071-06736



Photo 4 –TR wellhead



Photo 5 – TR Pit Facility, active pit. No pit permit on file