

Interim Reclamation and Stormwater Inspection

Date: 09/09/2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318096

Inspection Document #: 708201592

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Elkhorn CO #3
Location ID: 318096



Photo 1. Facing north at the start of the track out pad. It does not appear that any maintenance has been performed to the track out pad at the time of this inspection.

Inspection Photos
Location Name: Elkhorn CO #3
Location ID: 318096



Photo 2. Continued from Photo 1, facing north.

Inspection Photos
Location Name: Elkhorn CO #3
Location ID: 318096



Photo 3. Continued from Photo 1, facing south.

Inspection Photos
Location Name: Elkhorn CO #3
Location ID: 318096



Photos 4 & 5. Photos taken from WCR 20, facing east (left photo) and south (right photo). Photos illustrate vehicle track out onto county road.



Photo 6. Stained soil previously observed appears to have been disposed of at the time of this inspection.

Inspection Photos
Location Name: Elkhorn CO #3
Location ID: 318096



Photo 7. Trash remains around the southern portion of the tank battery location.

Inspection Photos
Location Name: Elkhorn CO #3
Location ID: 318096



Photo 8. Trash and debris previously observed at the well location appears to have been removed.