

Inspection Photos

September 9th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333992

Inspection Document #: 714001213

La Plata County, CO

Township: SWNE 20 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ute 1A-20 4
Location ID: 333992

9/9/24
+37.179989,-107.737542
237° SW



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos

Location Name: Ute 1A-20 4

Location ID: 333992




Photo 2. View of gully erosion observed in the southern portion of the interim reclamation area.

Inspection Photos
Location Name: Ute 1A-20 4
Location ID: 333992



Photo 3. Reference area comprised of Grama, Sabegrush and Juniper.