

# Inspection Photos

September 9th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325655

Inspection Document #: 714001214

La Plata County, CO

Township: NWNE 20 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Ute A1-20 2  
Location ID: 325655



**Photo 1.** View of the well disturbance taken from the access point facing center.



Inspection Photos  
Location Name: Ute A1-20 2  
Location ID: 325655



**Photo 2.** View of erosion observed forming in the southern interim reclamation area.



Inspection Photos  
Location Name: Ute A1-20 2  
Location ID: 325655



**Photo 3.** Reference area comprised of Grama, Sabegrush and Juniper.