

Inspection Photos

September 9th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325805

Inspection Document #: 714001216

La Plata County, CO

Township: SESW 21 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kennedy A1
Location ID: 325805



Photo 1. View of the well disturbance taken from the access point facing center.

Inspection Photos
Location Name: Kennedy A1
Location ID: 325805



Photo 2. View of flowering Musk and Canada thistle observed throughout the edges of the entire location.

Inspection Photos
Location Name: Kennedy A1
Location ID: 325805



Photo 3. View of impacted surface material at the well head.

Inspection Photos
Location Name: Kennedy A1
Location ID: 325805



Photo 4. View of surface owner trash, equipment and trailers observed stored in the eastern and southern portions of the disturbance.