

Inspection Photos

September 9th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326049

Inspection Document #: 714001217

La Plata County, CO

Township: SENW 28 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: McCaw C 1
Location ID: 326049



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the well disturbance taken from the access point facing center.
Note: No well/location sign observed on location.

API #: 067-07373

Inspection Photos
Location Name: McCaw C 1
Location ID: 326049



Photo 2. View of the eastern interim reclamation area facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07373

Inspection Photos
Location Name: McCaw C 1
Location ID: 326049

9/9/24
+37.165526,-107.726395
155° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area comprised of Rabbitbrush, Broom Snakeweed and Winterfat.

API #: 067-07373