

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403872554
Receive Date:
07/31/2024

Report taken by:
Chris Sanchez

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by ECOM is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>MURFIN DRILLING COMPANY INC</u>	Operator No: <u>61650</u>	Phone Numbers Phone: <u>(316) 858-8664</u> Mobile: <u>()</u>
Address: <u>250 N WATER ST STE 300</u>		
City: <u>WICHITA</u>	State: <u>KS</u>	Zip: <u>67202</u>
Contact Person: <u>Cristina Goodrich</u>	Email: <u>cgoodrich@murfininc.com</u>	

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 34350 Initial Form 27 Document #: 403644059

PURPOSE INFORMATION

- Rule 913.c.(1): Pit or Cuttings Trench closure.
- Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- Rule 913.g: Changes of Operator.
- Rule 915.b: Request to leave elevated inorganics in situ.
- Other: _____

SITE INFORMATION

Yes Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>009-06376</u>	County Name: <u>BACA</u>
Facility Name: <u>S E CAMPO UNIT 402W</u>	Latitude: <u>37.030923</u>	Longitude: <u>-102.567803</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NWNE</u>	Sec: <u>2</u>	Twp: <u>35S</u>	Range: <u>46W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

Facility Type: <u>LOCATION</u>	Facility ID: <u>321074</u>	API #: _____	County Name: <u>BACA</u>
Facility Name: <u>S E CAMPO UNIT-635S46W 2NWNE</u>	Latitude: <u>37.030923</u>	Longitude: <u>-102.567803</u>	
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>NWNE</u>	Sec: <u>2</u>	Twp: <u>35S</u>	Range: <u>46W</u> Meridian: <u>6</u> Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

Within Lesser Prairie Chicken Estimated Occupied Range HPH, within Lesser Prairie Chicken Connectivity Area HPH

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- | | | |
|--|--|--|
| <input checked="" type="checkbox"/> E&P Waste | <input type="checkbox"/> Other E&P Waste | <input type="checkbox"/> Non-E&P Waste |
| <input checked="" type="checkbox"/> Produced Water | <input type="checkbox"/> Workover Fluids | _____ |
| <input type="checkbox"/> Oil | <input type="checkbox"/> Tank Bottoms | |
| <input type="checkbox"/> Condensate | <input type="checkbox"/> Pigging Waste | |
| <input type="checkbox"/> Drilling Fluids | <input type="checkbox"/> Rig Wash | |
| <input type="checkbox"/> Drill Cuttings | <input type="checkbox"/> Spent Filters | |
| | <input type="checkbox"/> Pit Bottoms | |
| | <input type="checkbox"/> Other (as described by EPA) | _____ |

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	GROUNDWATER	NA	lab analysis if encountered
Yes	SOILS	TBD	lab analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

On 6/26/24, the wellhead cut & cap bellhole was assessed. Floor sample WH-FS-01@4' was submitted to Origins Laboratory in Denver, Colorado for full ECMC Table 915-1 analysis. Laboratory analytical results confirm TPH above Table 915-1 limit at WH-FS-01@4'. See attached site investigation report for all figures, tables, photos, lab reports and closure checklists for work completed to-date.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Excavation and confirmation soil sampling is needed at WH-FS-01@4'. On submitted I/SF19 403867216, Murfin requested a reduced analysis of TPH DRO & RRO only for wellhead excavation confirmation soil samples going forward.

Proposed Groundwater Sampling

Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

If groundwater is encountered during site assessment, a grab groundwater sample will be collected and analyzed for ECMC Table 915-1 Organic Compounds in Groundwater and Groundwater Inorganic Parameters.

Proposed Surface Water Sampling

Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Visual inspection of the injection line will occur during initial assessment activities. Field staff will use a PID to field screen a minimum of every 250' adjacent to the injection line to determine if laboratory analysis is required. Grab soil samples will be collected for lab analysis at change(s) in direction of the injection line as well as the end of the injection line at the isolation valve. If impacts are not apparent from visual, olfactory, and PID screening, the vertex and terminus injection line soil samples will be analyzed by a certified laboratory for full ECMC Table 915-1. If there are any apparent potential impacts, grab soil samples from those locations will be collected and analyzed for full ECMC Table 915-1. The ECMC Flowline Closure Checklist will be completed during the assessment and submitted on a Subsequent Form 27.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 1

NA Highest concentration of TPH (mg/kg) _____

Number of soil samples exceeding 915-1 1

NA Highest concentration of SAR _____

Was the areal and vertical extent of soil contamination delineated? No

BTEX > 915-1 No

Approximate areal extent (square feet) 1

Vertical Extent > 915-1 (in feet) 4

Groundwater

Number of groundwater samples collected 0

NA Highest concentration of Benzene (µg/l) _____

Was extent of groundwater contaminated delineated? No

NA Highest concentration of Toluene (µg/l) _____

Depth to groundwater (below ground surface, in feet) _____

NA Highest concentration of Ethylbenzene (µg/l) _____

Number of groundwater monitoring wells installed _____

NA Highest concentration of Xylene (µg/l) _____

Number of groundwater samples exceeding 915-1 _____

NA Highest concentration of Methane (mg/l) _____

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

Were impacts to adjacent property or offsite impacts identified?

Were background samples collected as part of this site investigation?

On 6/26/24, grab background soil samples were collected from 0.5', 3', and 4' at 2 separate locations off the pad perimeter in native area.

Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____

Volume of liquid waste (barrels) _____

Is further site investigation required?

See Proposed Sampling

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

No source has been generated.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

NA

Soil Remediation Summary

In Situ

Ex Situ

_____ Bioremediation (or enhanced bioremediation)

_____ Excavate and offsite disposal

_____ Chemical oxidation

_____ If Yes: Estimated Volume (Cubic Yards) _____

_____ Air sparge / Soil vapor extraction

_____ Name of Licensed Disposal Facility or ECMC Facility ID # _____

_____ Natural Attenuation

_____ Excavate and onsite remediation

Other _____

Land Treatment _____

Bioremediation (or enhanced bioremediation) _____

Chemical oxidation _____

Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the ECMC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Reclamation will be completed in accordance with ECMC 1000 Series Rules or as agreed upon with the Surface Owner.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

Interim

Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 01/04/2024

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 06/26/2024

Proposed site investigation commencement. 07/22/2024

Proposed completion of site investigation. 11/29/2024

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

Submitted I/SF19 document number 403867216 is related to this form. On submitted I/SF19 403867216, Murfin requested a reduced analysis of TPH DRO & RRO only for wellhead excavation confirmation soil samples going forward.

On 7/25/24, the surface owner, the United States Forest Service, requested that Murfin withhold all dirt work and excavation in the Campo Field until further notice while they review previous archeological surveys.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: David Castro

Title: Senior Project Scientist

Submit Date: 07/31/2024

Email: dcastro@eagle-enviro.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: Chris Sanchez

Date: 09/13/2024

Remediation Project Number: 34350

COA Type**Description**

	In addition, the Operator shall check the box for Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912. and add the Spill Facility ID to Site information as an additional facility.
	Operator shall define the vertical and lateral extent of impacts to soil. Additional sampling is required to fully delineate the vertical and lateral impacts to soil
	This Form 27 Supersedes Form 19 Document # 403867216, Operator shall collect Wellhead Confirmation samples for Full Table 915-1 Contaminants of Concern.
	Operator shall continue Quarterly Reporting until the Site Assessment is completed and the remediation area demonstrates Compliance with Table 915-1 Standards.

4 COAs

ATTACHMENT LIST

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403872554	INVESTIGATION/REMEDATION WORKPLAN (SUPPLEMENTAL)
403872618	SITE INVESTIGATION REPORT
403872619	SITE INVESTIGATION REPORT
403919903	FORM 27-SUPPLEMENTAL-SUBMITTED

Total Attach: 4 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)