

Inspection Photos

API: 071-08708

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 9/11/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. This culvert is filled in with sediment.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. There is erosion of the access road at the location that needs to be repaired.



Inspection Photos



Photo 3. Facing northwest at the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-08708 | Date: 9/11/2024

Inspection Photos



Photo 4. The pit material has been removed. It does not appear reseeding of this area has been completed and will need to be this fall.

