

# Inspection Photos

08/23/2024

**Operator:** SWN PRODUCTION COMPANY LLC -  
10396

**Location ID:** 311776

**Inspection Doc:** 696206215

Moffat County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 311776



August 23, 2024



August 23, 2024

**Photo 1:** Photos taken from the southeast end of the Location, facing northwest and north. Location has been reclaimed half cropland, half noncropland. Species planted are predominantly introduced species not reflective of perennial species in the reference. Areas of the Location remain bare, and access road has not been reclaimed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 311776



**Photo 2:** Photo example showing access road to the Location has not been reclaimed



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 311776



August 23, 2024



August 23, 2024

**Photo 3:** Photos 3-4 example of Undesirable and Noxious Plant species established on the Location. Weeds including Noxious species such as Common Mullein, Scotch thistle, Knapweed, Canada thistle. Areas of the Location also have not achieved uniform desirable vegetative establishment. Biennial species such as Sweet clover is dominant within northern areas of the reclamation (Photo right).



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 311776



**Photo 4:** See comments under photo 3. Photo left Canada thistle. Photo right also shows Location has been reclaimed half cropland, half noncropland



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 311776



**Photo 5:** Photos taken from the western half of the Location. Crop at time of inspection Safflower. Crop vegetative establishment on the well location/disturbance area is not reflective of the reference area. There are areas within the cropland areas of the Location where issues appear to exist that are hindering the reclamation of the location; crop establishment is thin, growth is stunted, and not reflective of crop established within adjacent undisturbed areas; compaction, remediation, or other issues may still exist within these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 311776



**Photo 6:** See comments under photo 5.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: SWN PRODUCTION COMPANY LLC - 10396

Location ID: 311776



**Photo 7:** Photo taken from the reference cropland areas west of the Location. Photo to compare crop establishment between reference and disturbance areas



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources