

Inspection Photos

September 9th, 2024

Operator: BMG Drilling Corporation - 7650

Location ID: 325388

Inspection Document #: 714001227

La Plata County, CO

Township: NENE 5 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: La Posta Canyon 4
Location ID: 325388

9/9/24
+38.045282,-108.637860
299° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the southern edge facing center.

API #: 067-06291

Inspection Photos
Location Name: La Posta Canyon 4
Location ID: 325388



Photo 2. View of start/end of germination transect conducted on location.

Inspection Photos
Location Name: La Posta Canyon 4
Location ID: 325388



Photo 3. View of gully erosion forming in the southern portion of the contoured cut slope with evidence of sediment transport.

Inspection Photos
Location Name: La Posta Canyon 4
Location ID: 325388



Photo 4. View of access road that has been broadcast seeded but not recontoured.

Inspection Photos
Location Name: La Posta Canyon 4
Location ID: 325388



9/9/24
+37.147454,-107.887540
48° NE

Photo 5. View of reference area comprised predominantly of Smooth brome and Rabbitbrush.