

Inspection Photos

API: 071-06406

Operator: OGRIS OPERATING LLC

Inspection Date: 9/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the reclaimed road. The perennial vegetation has re-established.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing southwest along the reclaimed road.



Inspection Photos



Photo 3. Facing west at the location which was recontoured. The perennial vegetation has re-established and the location is stabilized.



Inspection Photos



Photo 4. Facing south toward the lower portion of the reclaimed location.



Inspection Photos



Photo 5. Facing northwest toward the upper portion of the reclaimed location.



Inspection Photos



Photo 6. Facing back to the east at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources