

Inspection Photos

ID: 478058

Operator: OGRIS OPERATING LLC

Inspection Date: 9/16/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the main road to the production facility. The sediment along the roadside has been cleaned out to allow storwater drainage to the culvert.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024

Inspection Photos



Photo 2. Facing west at the road to the production facility. There are rock check dams that have already filled in with sediment and need to be cleaned out. A larger sediment catch may be better to prevent sediment transport onto the road. Also, round rock does not lock together and can easily be displaced.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024

Inspection Photos



Photo 3. Facing back toward the main public road. Sediment needs to be cleaned off the road and vehicle tracking controls need to be implemented.



Inspection Photos



Photo 4. Facing northwest toward the tank battery.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024

Inspection Photos



Photo 5. The netting on the open top tank does not cover the entire open top tank. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024

Inspection Photos



Photo 6. There is oily fluids in the secondary containment. Additionally netting must be installed to prevent wildlife entry. Previous CA was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024

Inspection Photos



Photo 7. Facing toward the tank battery. There still appears to be stained soils where trucks connect to the hoses.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 9/16/2024