

Operator: XOG

Location Name: Island Grove Directional 1

Loc ID: 423393

Inspection: 708201294



Exhibit A



Exhibit B



Exhibit C

CA: This location does not comply with Rule 1004. During this inspection, it was observed that the former access road does not appear to have been reclaimed with the presence of road base material and the reclaimed location is not progressing towards vegetative standards. Colorado List C Noxious Weeds (Cheatgrass and field bindweed), and undesirable vegetation (kochia) predominate the reclaimed areas. Additional reclamation activities are required. Refer to attached inspection photos. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has reported that the Fall seeding has now been completed, and location is in compliance with Rule 1004.

