

Inspection Photos

09/17/2024

Operator: CHEVRON USA INC #16700

Location ID: 323800

Inspection Doc: 696206238

Garfield County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 323800



Photo 1: Photos taken from the south end of the Location, facing northwest and north east. Final reclamation including, but not limited to, compaction alleviation, recontouring/regrading, replacement of topsoil, and revegetation activities have not been performed in accordance with 1004 Requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 323800



Photo 2: Pad surface. See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 323800



Photo 3: Photos taken from the cut slopes of the Location. Weeds have continued to establish on the Location. Erosion degradation also evident.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 323800



Photo 4: Photos taken from the southeast, and west ends of the Location. Photos show topsoil remains stockpiled, and has not been replaced; topsoil also remains predominantly bare.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 323800



Photo 5: Photo examples showing access road has not been reclaimed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources