

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403926685

Date Received:

09/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Caerus

COGCC.inspections@caerusoilandgas.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708904587

Inspection Date: 09/06/2024

FIR Submit Date: 09/15/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 432265

Location Name: Mamm Creek Number: J6SEB County: _____

Qtrqtr: NWSE Sec: 6 Twp: 8S Range: 92W Meridian: 6

Latitude: 39.387397 Longitude: -107.705592

FACILITY - API Number: 05-045-00 Facility ID: 432265

Facility Name: Mamm Creek Number: J6SEB

Qtrqtr: NWSE Sec: 6 Twp: 8S Range: 92W Meridian: 6

Latitude: 39.387397 Longitude: -107.705592

CORRECTIVE ACTIONS:

1 CA# 198779

Corrective Action: Comply with CECMC pressure safety device rules

Date: 09/22/2024

Response: CA COMPLETED

Date of Completion: 09/17/2024

Operator Comment: Installed cap on vent. See photo

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Justin Johnson

Signed:

Title: Compliance

Date: 9/18/2024 2:24:26 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403926687	Vent cap installed.

Total Attach: 1 Files