

**Operator: BCEI**

**Location Name: ANTELOPE 21-19 Pad**

**Loc ID: 418233**

**Inspection: 696306495**




Exhibit A

**CA:** L-19 (123-35125), 31-19 (123-32737) and K-19 (123-35127) Wellhead Signs have faded no longer visible. Install sign to comply with Rule 605.d.

**CA Resolution:** Operator has reported that signs have been appropriately updated for each of the listed wells to comply with the 600 series.



**Exhibit A**

**CA:** Unused Automation Equipment and Batteries at Wellsite; see photos. Comply with Rule 606.

**CA Resolution:** Operator has reported that unused automation equipment has been removed from the location to comply with Rule 606.