

Inspection Photos
Location Name: Seyfried 2
API # 05-123-14927



Sign



Inspection Photos
Location Name: Seyfried 2
API # 05-123-14927



Vegetation will need to be removed in the near future

Well

Inspection Photos
Location Name: Seyfried 2
API # 05-123-14927



Vegetation will need to be removed in the near future



Vegetation will need to be removed in the near future

Inspection Photos
Location Name: Seyfried 2
API # 05-123-14927



Unused Equipment



Tank needs secondary containment