

Final Reclamation and Stormwater Inspection

Date: 9/16/24

Operator: Klabzuba Oil & Gas Inc - 10148

Location ID: 393622

Inspection Document #: 713900985

Morgan County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Roark #1
Location ID: 393622



Photo 1. The photo was taken along the access road to the well location facing West. The photo illustrates the access road is still apparent.

Photo 2. The photo was taken at the well location facing North. The photo illustrates the well location remains disturbed with large areas of bare soil and subsidence.

Inspection Photos
Location Name: Roark #1
Location ID: 393622



Photo 3. The photo was taken at the well location facing East. Refer to the comment for photo 2.

Photo 4. The photo was taken at the well location facing South. Refer to the comment for photo 2.

Inspection Photos
Location Name: Roark #1
Location ID: 393622



Photo 5. The photo was taken at the well location facing West. Refer to the comment for photo 2.

Photo 6. The reference photo was taken near the well location facing North. The photo illustrates the location is not representative of nearby areas.