

Interim Reclamation and Stormwater Inspection

Date: 9/16/24

Operator: PCR Operating LLC - 10657

Location ID: 313696

Inspection Document #: 713900991

Morgan County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: AJU Johnson-GLN #1

Location ID: 313696



Photo 1. The photo was taken at the entrance to the well location facing Southwest. The photo illustrates the Operator location sign emergency contact and operator stickers still need replaced.



Photo 2. The photo was taken at the well location facing West. The photo illustrates unmanaged weeds growing around the wellhead.

Inspection Photos
Location Name: AJU Johnson-GLN #1
Location ID: 313696



Photo 3. The photo was taken at the well location facing North. The photo illustrates unused debris scattered around the well location.



Photo 4. The photo was taken at the well location facing Northeast. Refer to the comment for photo 3.

Inspection Photos
Location Name: AJU Johnson-GLN #1
Location ID: 313696



Photo 5. The photo was taken at the well location facing Northeast. Refer to the comment for photo 3.



Photo 6. The photo was taken at the well location facing Northeast. Refer to the comment for photo 3.

Inspection Photos
Location Name: AJU Johnson-GLN #1
Location ID: 313696



Photo 7. The photo was taken at the well location facing West. Refer to the comment for photo 3.

Inspection Photos
Location Name: AJU Johnson-GLN #1
Location ID: 313696



Photo 8. The photo was taken at the well location facing Southwest. The photo illustrates interim areas.