

Inspection Photos

Date of Inspection: 9/19/24

Operator: Dover Atwood/Envex-Baca LLC

Location Name: Grizzly 1-34 API: 009-06607



Brian Welsh SE Field Inspector COGCC
09/19/2024 11:07:43

1. Location overview



Brian Welsh SE Field Inspector COGCC
37.38735, -102.25072, 3819.6ft
09/19/2024 11:08:59

2. Pumping unit and wellhead



Inspection Photos

Date of Inspection: 9/19/24

Operator: Dover Atwood/Envex-Baca LLC

Location Name: Grizzly 1-34 API: 009-06607



Brian Welsh SE Field Inspector COGCC
37.38728, -102.25075, 3811.0ft
09/19/2024 11:09:11

3. Looking south at water tanks



Brian Welsh SE Field Inspector COGCC
37.38726, -102.25074, 3783.1ft
09/19/2024 11:11:00

4. East side of water tanks

