

Inspection Photos
Operator: Dover Atwood/Envex-Baca LLC
Location Name: Clays 1 API: 009-06234



Brian Welsh SE Field Inspector COGCC
37.35406, -102.21173, 3734.0ft
09/19/2024 13:26:09

1. Pumping unit and water tank



Brian Welsh SE Field Inspector COGCC
37.35399, -102.21171, 3734.7ft
09/19/2024 13:26:28

2. Weeds around water tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Insp #715200982

Inspection Photos
Operator: Dover Atwood/Envex-Baca LLC
Location Name: Clays 1 API: 009-06234



**3. Meter shed with lease sign.
Lease sign is faded**



**4. Pack rat has a nest in the meter
shed that needs cleaned out.**