

Inspection Photos

September 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326271

Inspection Document #: 714001243

La Plata County, CO

Township: SWSE 1 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Richardson G1
Location ID: 326271

9/18/24
+37.239945,-107.693469
23° NE



9/18/24
+37.239945,-107.693531
23° NE

Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07752

Inspection Photos
Location Name: Richardson G1
Location ID: 326271



Photo 2. View of rill erosion issues persisting in the western portion of the disturbance, stormwater BMPs/additional stabilization are needed in this area.

Inspection Photos
Location Name: Richardson G1
Location ID: 326271



Photo 3. Reference area comprised of Pine, Juniper and Sagebrush.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07752