

Inspection Photos

September 18th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325839

Inspection Document #: 714001244

La Plata County, CO

Township: SWNW 1 34N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Burkett A1
Location ID: 325839

9/18/24
+37.247292,-107.701170
280° W



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-07059

Inspection Photos
Location Name: Burkett A1
Location ID: 325839



Photo 2. View of active erosion and sediment transport occurring on the northern edge of the active pad. Stormwater BMPs are needed in this area.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07059

Inspection Photos
Location Name: Burkett A1
Location ID: 325839



Photo 3. View of check dams along access road that are filled with sediment and no longer functioning.

Inspection Photos
Location Name: Burkett A1
Location ID: 325839



9/18/24
+37.246530,-107.699799
91° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of severe sediment deposition occurring at the location access point, as deep as a 10 inches in some areas.

API #: 067-07059