

Final Reclamation and Stormwater Inspection

Date: 09/10/2024

Operator: ST CROIX OPERATING INC - 81490

Location ID: 469079

Inspection Document #: 708201605

Washington County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photo 1. Southeast corner of the location. The well location (Location ID 469079 with API #121-11089) meets final reclamation regulations and standards. Unable to find evidence of oil and gas activities and/or disturbances. The reclaimed location appears to be reflective of the adjacent reference area. Perimeter fencing will need to be removed and the location will need to be re-inspected at a later date, therefore, this location will remain “In-Process” until the fence is removed.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photo 2. Northeast corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photo 3. Northwest corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079




Photo 4. Southwest corner of the location; see comments in Photo 1.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079




Photos 5-8. Disturbance area transect start point, facing cardinal directions.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photos 9-12. Disturbance area transect mid point, facing cardinal directions.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photos 13-16. Disturbance area transect end point, facing cardinal directions.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photos 17-20. Reference area transect start point, facing cardinal directions.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photos 21-24. Reference area transect mid point, facing cardinal directions.

Inspection Photos
Location Name: State Little Joe #1
Location ID: 469079



Photos 25-28. Reference area transect end point, facing cardinal directions.

