



WELLHEAD ABANDONMENT FORM

SITE NAME: WHEELER 1-21A							DATE: 6/12/2024	REM. PROJECT #:	WEATHER: 95 SUNNY		
SITE DIRECTIONS: CR 31 S CR 20 W .25 S TO SITE E							CLIENT: Anadarko				
LEGALS AND LAT/LONG:							TASMAN PERSONNEL: DE,KM				
SOIL TYPES: Silty Sand - SM							SURFACE GRADIENT: West				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
6/12/2024 14:30	WH-B01@6'	0.0	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel				
6/12/2024 14:32	WH-N01@5'	0.0	No Staining	No Odor	Yes	N/A	Separator				
6/12/2024 14:34	WH-S01@5'	0.0	No Staining	No Odor	Yes	N/A	Emission Control Device (ECD)				
6/12/2024 14:36	WH-E01@5'	0.0	No Staining	No Odor	Yes	N/A	Dump Line				
6/12/2024 14:38	WH-W01@5'	0.0	No Staining	No Odor	Yes	N/A	Wellhead				
6/12/2024 14:40	FL-B01@4'	0.1	No Staining	No Odor	Yes	Lab	Flowline				
6/12/2024 14:42	WHS-N01@3"	0.1	No Staining	No Odor	Yes	N/A	Other:				
6/12/2024 14:44	WHS-S01@3"	0.0	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
6/12/2024 14:46	WHS-E01@3"	0.0	No Staining	No Odor	Yes	N/A	IMPACTED SOIL IDENTIFIED?				
6/12/2024 14:48	WHS-W01@3"	0.1	No Staining	No Odor	Yes	N/A	ESTIMATED VOLUME OF IMPACTS:				
6/12/2024 14:50	BG01@3'	2.0	No Staining	No Odor	Yes	Lab	Date	Number	CY		
6/12/2024 14:52	BG01@6'	1.3	No Staining	No Odor	Yes	Lab					
6/12/2024 14:54	BG02@3'	1.3	No Staining	No Odor	Yes	Lab					
6/12/2024 14:56	BG02@6'	3.2	No Staining	No Odor	Yes	Lab					
6/12/2024 14:58	BG03@3'	1.8	No Staining	No Odor	Yes	Lab					
6/12/2024 15:00	BG03@6'	1.6	No Staining	No Odor	Yes	Lab	Total Removed		0	0	
6/12/2024 15:02	BG04@3'	1.9	No Staining	No Odor	Yes	Lab	Disposal Facility:				
6/12/2024 15:04	BG04@6'	1.0	No Staining	No Odor	Yes	Lab	Groundwater Recovery				
6/12/2024 15:06	BG05@3'	1.5	No Staining	No Odor	Yes	Lab	DATE GW ENCOUNTERED:			DEPTH:	
6/12/2024 15:08	BG05@6'	2.0	No Staining	No Odor	Yes	Lab	GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
6/12/2024 15:10	BG06@3'	0.6	No Staining	No Odor	Yes	Lab					
6/12/2024 15:12	BG06@6'	0.9	No Staining	No Odor	Yes	Lab	LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLs		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
6/13/2024 15:52	GW-FL-B02@4'	4'	Low Turbidity	None	None	Yes					
							Total Removed		0		
							Disposal Facility:				




Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			