

**Inspection Photos**  
**Location: Kern Estate 1**  
**Location ID: 314174**  
**API # 05-099-06045**



**Photo 1 –Well placard on meter house**



**Photo 2 – Wellhead and equipment, Impacted soils  
at blue arrow**



**Inspection Photos**  
**Location: Kern Estate 1**  
**Location ID: 314174**  
**API # 05-099-06045**



**Photo 3 – Heater Treater**



**Photo 4 – Area of impacted soils**



**Inspection Photos**  
**Location: Kern Estate 1**  
**Location ID: 314174**  
**API # 05-099-06045**



**Photo 5 – Area of impacted soils**




**Photo 6 – Area of impacted soils**

**Inspection Photos**  
**Location: Kern Estate 1**  
**Location ID: 314174**  
**API # 05-099-06045**



**Photo 7 – Area of impacted soils**



**Photo 8 – PID Reading at 38.08150, -102.70951**



**Inspection Photos**  
**Location: Kern Estate 1**  
**Location ID: 314174**  
**API # 05-099-06045**



**Photo 9 – Impacted materials observed near Heater Treater**



**Photo 10 – Areas of impacted soils**

