

Inspection Photos
Location Name: ROTHE-65N63W/29SESW
Location #: 302303



Colorado Energy & Carbon Management Commission
Weld County
+40.366629, -104.464499
250° W
2024-09-26 13:50

Photo #1

Rothe 29BU (123-28108) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 30 yds.



Colorado Energy & Carbon Management Commission
Weld County
+40.366432, -104.464271
218° SW
2024-09-26 13:53

Photo #2

Rothe 29BU, 13-29U, 14-29U, 23-29U, 24-29U

Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (5-Wells)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources