

## Inspection Photos

Location Name: ROTHE-65N63W/29SWSW

Location #: 306702



**Photo #1**

**Rothe 14-29U (123-25134) Wellsite**

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 90 yds.*



**Photo #2**

**Rothe 29BU, 13-29U, 14-29U, 23-29U, 24-29U**

**Battery site**

**Abandoned: ALL Equipment Removed**

**Plugged & Abandoned | PA (5-Wells)**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources