

Inspection Photos  
Location Name: BOX ELDER 27-1  
Location ID: 320278



Photo#1 Wellhead

Photo#2 Stained soil around ground valve at wellhead

**Inspection Photos**  
**Location Name: BOX ELDER 27-1**  
**Location ID: 320278**



**Photo#3 Stained soil around ground valve at wellhead**

**Photo#4 Separator/ECD**

**Inspection Photos**  
**Location Name: BOX ELDER 27-1**  
**Location ID: 320278**



**Photo#5 Production Tanks/Weeds**



**Photo#6 Oil appears to be leaking from thief hatch going down the side of the production tank**

**Inspection Photos**  
**Location Name: BOX ELDER 27-1**  
**Location ID: 320278**



**Photo#7 Weeds**

**Photo#8 Production Tank/Produced water vault**