

Inspection Photos
Location Name: BOX ELDER 13-28
Location ID: 320455



Photo#1 Wellhead/**Weeds**

Photo#2 Separator/ECD/**Weeds**

Inspection Photos
Location Name: BOX ELDER 13-28
Location ID: 320455



Photo#3 Production Tank/WEEDS

Photo#4 PRV appears to be leaking