

Inspection Photos
Location Name: BOX ELDER 22-28
Location ID: 320454



Photo#1 Wellhead/**WEEDS**



Photo#2 Separator/ECD/**WEEDS**



Inspection Photos
Location Name: BOX ELDER 22-28
Location ID: 320454



Photo#3 Production Tank/**WEEDS**



Video#1 Wellhead leaking gas below the tubing nut

